



WHITE



BLACK



C: 100% M: 10% K: 10%



M: 100% Y: 100%

CAUTION: Turn off power before use.

1. Strip stranded wires 12 mm (0.47").
2. Pretwisting unnecessary.
Hold stripped wires together with ends even (lead stranded wires slightly).
3. Align any frayed strands or conductors.
4. Screw on connector—push wires firmly into connector when starting.
5. To be sold only with installation instructions.

LISTED FOR USE WITH
COPPER TO COPPERInsulation operating temperature:
105°C (221°F) Max.

623-002



Twist-on Wire Connectors

Quantity: 100

Listed as splicing wire connectors
on the following stranded wire combinations:
Voltage: 300V Max.

1 #18 w/ 1 #16 w/ 1 #14	1 to 4 #22 w/ 1 #16
1 #22 w/ 1 #20 w/ 1 or 2 #16	1 or 2 #20 w/ 3 #18
1 #22 w/ 1 #20 w/ 1 or 2 #18	1 or 2 #22 w/ 3 #18
1 to 3 #20 w/ 1 #14	1 to 3 #20 w/ 2 #18
1 to 4 #22 w/ 1 #14	1 to 3 #22 w/ 2 #18
2 or 3 #16	2 to 4 #20 w/ 1 #18
2 to 4 #18	3 or 4 #22 w/ 1 #18
3 to 5 #22	1 or 2 # 22 w/ 3 #20
1 #18 w/ 2 #16	2 or 3 # 22 w/ 2 #20
1 to 3 #22 w/ 2 #16	4 #22 w/ 1 #20
1 or 2 #18 w/ 1 #16	
1 to 4 #20 w/ 1 #16	

LISTED
WIRE CONNECTOR
38EY
E336143

Made in China



48 mm

159 mm